



Before

- Access obstructed by parking
- Poor visibility of walking route
- Untidy tree undergrowth
- Focus for litter and dumping
- Poor maintenance
- Narrow and off-putting approach to bridge



Now

- Parking removed
- Clear visibility of walking route
- High quality landscaping
- A welcoming entrance to the Wandle Valley Regional Park

This page is intentionally left blank